

**To:** Killian, Richard[killian.richard@epa.gov]  
**Cc:** Jimenez, Jose[JIMENEZ.JOSE@EPA.GOV]  
**From:** Crutchley, Gerard  
**Sent:** Mon 6/24/2013 10:51:38 AM  
**Subject:** Super Salvage

Rich,

Here is a list of the samples that were taken at Super Salvage on 5/29/13:

Sample # SS1 – large trash can under dust collection unit on old blast booth – requested analysis TCLP metals

Sample # SS2 – open plastic drum behind old blast booth – requested analysis TCLP metals

Sample # SS3 – dust on floor next to plastic trash can adjacent to old blast booth – requested analysis TCLP metals

Sample # SS4 – sediment near north end of pond – requested analysis TCLP metals

Sample # SS5 – oily water from pond – requested analysis DRO, PAH, and metals.

All of the samples remained our custody (me & Justin) and were delivered to the Region III lab at Fort Meade for analysis. The usual turn around time for samples is 45 days; however, I can probably get some preliminary numbers this week.

Jerry